


NOMAD

SURFACE TO SURFACE MISSILE

SKILL LEVEL 2 – Recommended for Intermediate Rocketeers.

BEFORE YOU START

Read all instructions before beginning work on your model. Make sure you have all parts and materials. When you are thoroughly familiar with the assembly procedure, begin construction. Check off each step as you complete it. In each step, test-fit the parts together before applying any glue. If some part doesn't fit properly, sand lightly or build-up as needed for precision assembly.



PARTS LIST KIT NO. 1344

- A 2 Nose Cone Halves (type PNC-20ED) 71006
- B 2 Tube Adapter Halves (type PTA-2050) 30100
- C 1 Engine Mount Tube (type BT-20J) 30326
- D 1 Engine Hook (type EH-2) 35025
- E 2 Adapter Rings (type AR-2050) .30164
- F 1 Shock Cord Mount (type SCM-50) 84444
- G 1 Shock Cord (type SC-1) 85730
- H 2 Fin Unit Halves (type PFU-54ED) 32412
- I 1 Body Tube (type BT-50) 30352
- J 1 Body Tube (type BT-20) 30316
- K 1 Launch Lug (type LL-2A) 38175
- L 1 Parachute (type PK-12A) 85564
- M 1 Shroud Line (type SLT-72) .. 38237
- N 1 Tape Discs (type TD-3F) 38406
- O 1 Decal (type KD-1344) 37151

TOOLS AND MATERIALS

In addition to the parts included in this kit you will need tube-type plastic cement, white glue (Titebond, Elmer's or similar household white glue is recommended.), scissors, pencil, rubber bands, modeling knife, copper enamel spray paint, gloss white enamel spray paint, and aircraft gray spray paint.

RECOMMENDED ENGINES:
A8-3 B4-4 B6-4 B8-5 B14-5 C6-5 C6-7

